

No: 01/2013

Date : 17 January 2013

AIRPORT EMERGENCY SERVICE

FIRE SAFETY CIRCULAR

To All Airport Staff and Partners

SMOKING IN NON-DESIGNATED AREAS IN CHANGI AIRPORT

The AES regularly receives feedback from external parties of illegal smoking in various locations in Changi Airport and attends to burning smell cases caused by illegal smoking activities (see selected locations at Annex A). Such activities contravene the National Environment Agency (NEA) regulations as well as lead to the unnecessary turn-out of AES firefighting resources.

2 We seek the cooperation of all airport partners to remind their staff to smoke only at designated areas. AES will not hesitate to issue a service charge (of SGD350 per vehicle per hour or part thereof excluding prevailing government taxes) for the unnecessary turn-out of AES firefighting resources due to illegal smoking in non-designated areas and also refer offenders to their employers and/or NEA for further action.

3 For more information, please contact the AES FSU at 65412535, email to fire.safety@changiairport.com or refer to the fire safety manual at <u>http://www.changiairportgroup.com/cag/html/our-services/airport-emergency-services/fire-safety</u>

NAZRI BAMADHAJ 1 STAFF OFFICER, FIRE SAFETY for SUPERINTENDENT, FIRE SAFETY Annex A

Burning Smell Incident at Terminal 2, Basement North near to lift lobby no. 15 & 16 caused by illegal smoking



Staircase landing, B16-STR-01

Cigarette butts found behind staircase landing

Non-Designated Smoking Area @ 'D' Pier Ext, Staircase 2 between Bay D 36 & 35



Area used as smoking area & littered with cigarette butts and other rubbish



Two GHA Staff were found smoking in the staircase landing