No : 15 / 2022

Date : 29 Nov 2022



## AIRPORT EMERGENCY SERVICE

## FIRE PREVENTION CIRCULAR

To All Airport Staff and Tenants

## PRECAUTION AGAINST UNWANTED FIRE ALARM ACTIVATION

There were several occurrence of airport staff and tenants creating unwanted fire alarm activation when they operated equipment in their premises, that produce steam or smoke, below or near the vicinity of smoke detectors. Examples of such occurrence are: - the placing of food or beverage steamer below or near the vicinity of a smoke detector; and the ironing or steaming of clothes below or near the vicinity of a smoke detector.

- The smoke detector is activated when smoke is detected. The activation of the smoke detector will result in resources from the security agencies and AES responding to the premises. To prevent unwanted fire alarm activation, all airport staff and tenants are advised to position equipment that produce steam or smoke away from the smoke detectors.
- A service charge of at least \$600 will be issued to tenants for unwanted fire alarm activation.
- For any clarification, please contact the AES Fire Prevention Section at 6541 2535 or email at: <a href="mailto:fire.safety@changiairport.com">fire.safety@changiairport.com</a>.

ADDISON LOW

Head, Fire Prevention Section Airport Emergency Service